

PÓŁSRUBUNEK PRZYŁĄCZENIOWY

MATERIAŁ


Mosiądz CW614

CIŚNIENIE ROBOCZE

PN16bar




Grzybek



G	L1	L7	D2	D3	D10
---	----	----	----	----	-----

1/2" x 1/2"	1/2"	31,7	1,5	16,0	11,0	11,0
3/4" x 3/4"	3/4"	39,5	2	19,5	16,3	14
1" x 1"	1"	40	2	25,5	17	19
1 1/4" x 1 1/4"	1 1/4"	45	2	33,2	20	22
1 1/2" x 1 1/2"	1 1/2"	45	2	40	32	25
2" x 2"	2"	50	2,5	64	51	49

Nakrętka



G	L1	L2	L3	D1
---	----	----	----	----

1/2" x 1/2"	1/2"	24	12	10,5	17
3/4" x 3/4"	3/4"	29	12,5	11	21
1" x 1"	1"	35	15	13	26
1 1/4" x 1 1/4"	1 1/4"	45	18	16	16
1 1/2" x 1 1/2"	1 1/2"	52	20	17	42
2" x 2"	2"	65	24,5	18,5	48,5